

Article

Not peer-reviewed version

Smart Road Maintenance: Using Smart Technologies for Maintenance Management on Local Roads

[Laura Fabiana Jáuregui Gallegos](#) , [Rubén Gamarra Tuco](#) ^{*} , [Alain Jorge Espinoza Vigil](#) ^{*}

Posted Date: 27 September 2024

doi: 10.20944/preprints202409.2175.v1

Keywords: Road Management; Maintenance Road Management; PCI; IRI; Local Roads; Smart Road Maintenance; Smart Technologies



Preprints.org is a free multidiscipline platform providing preprint service that is dedicated to making early versions of research outputs permanently available and citable. Preprints posted at Preprints.org appear in Web of Science, Crossref, Google Scholar, Scilit, Europe PMC.

Copyright: This is an open access article distributed under the Creative Commons Attribution License which permits unrestricted use, distribution, and reproduction in any medium, provided the original work is properly cited.

Article

Smart Road Maintenance: Using Smart Technologies for Maintenance Management on Local Roads

Laura Fabiana Jáuregui Gallegos, Rubén Gamarra Tuco and Alain Jorge Espinoza Vigil *

School of Civil Engineering, Universidad Católica de Santa Maria, San Jose Urbanization, Yanahuara District, Arequipa 04013, Peru

* Correspondence: aespinozav@ucsm.edu.pe

Highlights:

This is an obligatory section in “Smart Cities”, whose goal is to increase the discoverability and readability of the article via search engines and other scholars. Highlights should not be a copy of the abstract, but a simple text allowing the reader to quickly and simplified find out what the article is about and what can be cited from it. Each of these parts should be devoted up to 2 bullet points.

What are the main findings?

- A new proposal was developed to manage the maintenance of local roads under the responsibility of local governments, through the use of efficient, effective, and low-cost smart technologies.
- The Roadroid app was used to evaluate the International Roughness Index (IRI), and the Mavic 2 Pro drone was used to assess the Pavement Condition Index (PCI) on the AR-780 road in Polobaya. The results indicate that Roadroid and the Mavic 2 Pro are 24.42% and 73.64% more cost-effective, respectively, compared to traditional methodologies. Additionally, both tools proved to be 60 and 10 times more efficient, respectively, compared to conventional methods. The variation in accuracy between Roadroid and traditional methodologies was 8.71%, while for the Mavic 2 Pro, it was 6.89%.

What is the implication of the main finding?

- Improved maintenance management for local roads so that the stakeholders responsible for the roads can make science-based decisions and thus contribute to the well-being of the population.
- It offers an efficient and cost-effective road maintenance management proposal that can be used by local governments with limited economic resources, allowing them to monitor their roads and apply the necessary repair actions.

Abstract: This research seeks to provide local governments with a comprehensive alternative for the proper maintenance of roads, focusing on the surface and functional evaluation of pavements. It compares conventional methods of the International Roughness Index (IRI) and the Pavement Condition Index (PCI) with novel methodologies that employ smart technologies. Road maintenance is essential for economic development, facilitating the circulation of services and resources. This research analyzes the efficiency of smart technologies in the maintenance of local roads in Arequipa, taking as a case study a 2 km section of the AR-780 highway in Polobaya. The International Roughness Indices (IRI) obtained through the Merlin Roughness Meter and the Roadroid application were compared, finding a minimum variation of 4.007% in the left lane and 8.5% in the right lane. Roadroid turned out to be 60 times faster than the conventional method, with a cost difference of 220.11 soles. Both methods classified the road condition (PSI) as GOOD, validating the accuracy of Roadroid. In addition, the Pavement Condition Index (PCI) was evaluated with conventional methods and a DJI Mavic 2 Pro drone, finding a variation of 6.89%. The cost difference between the methodologies was 1,047.73 soles, and the use of the drone proved to be 10 times faster than visual inspection. Finally, it can be said that this study contributes to closing the knowledge gap regarding the use of smart technologies for better pavement

management on local roads, so that the actors in charge of the roads can make decisions based on science and thus contribute to the well-being of the population.

Keywords: road management; maintenance road management; PCI; IRI; local roads; smart road maintenance and smart technologies

1. Introduction

Road infrastructure is a fundamental pillar for the development and efficient functioning of global economies, facilitating the flow of goods, services, and resources between different regions. In this context, the proper maintenance of transportation routes, especially pavements, is crucial [1]. This process not only optimizes the comfort and safety of users but also preserves the functionality of the pavement, ensuring essential features such as skid resistance and a suitable appearance, while also reducing associated operational costs [2]. Consequently, it is imperative to design, build, and maintain road infrastructures appropriately, guaranteeing their long-term durability and safety [3].

In the specific case of Peru, despite global technological advancements, the country lacks an efficient monitoring system that allows for the accurate assessment of its infrastructure [4], including roadways. Some methodologies have been proposed to evaluate the condition of bridges [5–7], mainly in response to hydrological phenomena such as El Niño, which significantly affects infrastructure [8]. However, there is little literature on pavement conservation plans to properly prioritize maintenance and potential pavement redesign, which should occur periodically to monitor its condition and attempt to predict its future state [9]. This deficiency has significant repercussions, particularly in the economic realm, as it affects the durability of roads and increases associated operational costs [10].

Pavement evaluation provides essential information for both its design and management. Through this evaluation, it is possible to determine the necessary interventions to ensure proper functionality, whether through maintenance, rehabilitation, or reconstruction [11]. This process also allows for a more accurate estimation of the costs associated with the required interventions, thus optimizing planning and resource allocation [12].

In this research, two types of evaluations were conducted: functional and surface evaluations. The functional evaluation focuses on analyzing the International Roughness Index (IRI), which measures the smoothness of the pavement surface [2]. Knowing this index is crucial for defining conservation or rehabilitation actions, as surface irregularities not only affect vehicle performance but also increase pavement deformation, leading to higher rehabilitation and maintenance costs [13]. On the other hand, the surface evaluation is based on analyzing the Pavement Condition Index (PCI). Quantifying this index allows for efficient management of the necessary interventions for pavement treatment and maintenance, thereby ensuring its optimal conservation [14]. Both indices are essential for road evaluation, and their effectiveness is enhanced by using modern and low-cost techniques [15]. These tools enable efficient monitoring of pavement conditions, which optimizes municipal governments' use of resources in infrastructure management. This approach is crucial for ensuring sustainable and effective road network maintenance [1].

Therefore, the aim of this research is to propose an approach for the implementation of smart technologies in the management of local road maintenance. It is worth noting that the responsibility for these roads falls on local governments or municipalities [16]. From this context, the research seeks to answer the question: What does the use of smart technologies for local road maintenance management involve? To address this question, five specific objectives have been defined:

- Determine the roughness value using the traditional Merlín Roughness Meter method and compare it with Roadroid.
- Determine the pavement quality using the present serviceability index (PSI) with the Merlín Roughness Meter and Roadroid.

- Determine the PCI through a conventional failure inspection and compare it with an inspection using drones.
- Establish the intervention range for local roads based on the PCI obtained through visual failure inspections and drone flights.
- Evaluate the efficiency of using smart technologies in the management of local road maintenance.

The research is based on an exhaustive literature review, which is presented in Chapter 2, detailing the state of the art. Chapter 3 outlines the main research methods used, including the case study. Chapter 4 contains flow figures corresponding to the four methodologies employed to meet the specific objectives. Chapter 5 presents the results obtained during the research, while Chapter 6 is dedicated to discussing those results. Finally, Chapter 7 comprises the conclusions drawn from the study.

2. State of the Art

Table 1 outlines research backgrounds, the methods employed, and the relevance of each study to the case study.

Table 1. Research background.

ID	AUTHOR	YEAR	RESEARCH METHODS	RELEVANCE	CASE STUDY
A1	[12]	2018	Roadroid	IRI value obtained and SDI value determined.	Jenderal Sudirman Kalianget Road – Indonesia
A2	[17]	2018	Roadroid and Visual Inspection for PCI	Correlation of pavement PCI with IRI.	Magetan District Road – Indonesia.
A3	[18]	2019	Roadroid and Visual Inspection for PCI	Determine PCI and serviceability level.	Lucre-Huacarpay Avenue—Peru.
A4	[19]	2021	Abakal and Roadroid	Calculate IRI and PSI.	Antunez de Mayolo Avenue—Peru.
A5	[14]	2021	Roadroid and ROOGA equipment	Compare IRI using the application and ROOGA equipment with leveling.	Covadonga Road, Ayacucho.
A6	[15]	2021	DJI Phantom 4 Pro V2.0 Drone	Determine PCI.	Los Conquistadores Avenue, Lima.
A7	[11]	2021	Laser profilometer and Roadroid	Compare IRI and PSI.	Concession No. 3: Mocupe, Lambayeque.
A8		2022	Roadroid and Merlin Roughness Meter Method	Compare IRI and PSI with their respective correlation coefficients.	Prolongation Iquitos Avenue, Javier Prado Avenue, and Petit Thouars Avenue, Lima.
A9	[1]	2019	Drone and Visual Inspection	Compare PCI between both methodologies.	Separadora Industrial Avenue, blocks 8-10, Ate, Lima—Peru.

A10	[9]	2017	Visual Inspection	Calculate PCI and provide maintenance proposals.	Ramón Castilla Avenue, Chulucanas, Piura.
A10	[13]	2021	Systematic Literature Review	Evaluate the efficiency of PCI and IRI for assessing serviceability through various studies.	Literature review of different indexed articles.
A11	[20]	2023	Systematic Literature Review	Evaluate current trends in the implementation of smart technologies for road construction and maintenance.	Literature review of different indexed articles.

Regarding the table above, it is noteworthy that several authors have used the Roadroid application in their research, making comparisons with various methodologies, such as the PCI method through visual inspection, the use of the Abakal application, the ROOGA equipment, and the laser profilometer. Each of these approaches aims to calculate the surface regularity of roads. The main differences between these studies lie in the type of roads analyzed (highways, roads, local roads, and urban streets), while a notable similarity is the high effectiveness reported for the Roadroid application. This finding represents a positive precedent for the present research, which seeks to identify smart technologies for the efficient management of road infrastructures.

Additionally, the table presents the evaluation of the Pavement Condition Index (PCI) using various methodologies, such as visual inspection and the use of advanced technology, specifically the DJI Phantom 4 drone. According to [15], the most notable difference between both techniques is that smart technology, represented by the drone, significantly reduces evaluation time while showing accuracy comparable to that of the conventional method. This finding is highly relevant to the present research, as it establishes a positive precedent in the search for efficient alternatives for the management of local roads.

3. Methodology

The research methodology includes methodological schemes, detailed below through four figures, which address the first four specific objectives, focusing on the case study of the AR-780 local road in Arequipa. The general data for the AR-780 road in Polobaya, Arequipa are as follows: pavement type: flexible, length: 2 km, road width: 7.6 m.

Figure 1, corresponding to the first flowchart, summarizes the methodology for determining the Pavement Condition Index (PCI) using the Merlin Roughness Meter. The procedure begins with calibrating the equipment by placing it on a horizontal surface and adjusting its support points until the pointer indicates 25. If it doesn't, the lower bolts are adjusted until this is achieved. Then, two readings are taken: an initial one (RI) and another with a calibration block under the movable foot (Rf) to determine the correction factor. Three people are required: an operator, an assistant to record the readings and a spotter. The operator moves the equipment until the wheel completes one rotation (1.98 m), places it on its three support points, and records the pointer's position in a field form, repeating the process until 200 consecutive readings are completed. The recording form has 20 rows and 10 columns, filled from top to bottom and left to right.




Figure 1. Flowchart of the Rugosimeter Merlin Equipment method.

Figure 2, corresponding to the second flowchart, summarizes the methodology for determining the Pavement Condition Index (PCI) using the Roadroid application. The procedure begins by creating an account on the Roadroid website, where personal data and the phone's IMEI are registered. The license can be free for educational purposes or purchased on the site. After registration, the phone is calibrated to ensure no data is lost. A mount for the phone must be installed on the vehicle's windshield, ensuring a horizontal position without obstructions. To perform the pavement roughness index (IRI) diagnosis, the GPS and Wi-Fi or mobile data are activated. The app settings, such as vehicle type, are adjusted, and the phone is calibrated. Once calibrated, the

diagnostic process begins by pressing the camera button, and the vehicle should move at 50 km/h. The data is uploaded to the Roadroid system using Wi-Fi. These can be viewed on a virtual map after 15-20 minutes, and reports can be generated and downloaded in formats like KML or TXT for analysis in programs like ArcGIS or Excel [21].




Figure 2. Flowchart of the Roadroid method.

Figure 3, corresponding to the third flowchart, summarizes the procedure for measuring the PCI through visual inspection. To calculate it, the failure data obtained during the on-site inspection according to the 19 specified failures is required. These values are then subjected to the following steps: the Deduct Value (DV) is calculated by recording the sum of each type of failure according to its severity and quantity. The density of the failures is then used to determine the deducted value for each type of damage. Next, the maximum allowable deducted values (m) are calculated using an equation that takes into account the maximum deducted value for each sampling unit. The total deducted value is adjusted using a correction curve, thus obtaining the maximum Corrected Deduct Value (CDV). Finally, the PCI is calculated by subtracting the maximum CDV from 100, which indicates the pavement's condition. The PCI is classified according to various failures such as deformations, cracks, and erosion in the pavement [22].




Figure 3. Procedure for measuring PCI by visual inspection.

Figure 4, corresponding to the fourth flowchart, summarizes the procedure for measuring the PCI using the DJI Mavic 2 Pro drone, programmed via a mobile phone with the DJI PILOT app. The flight was conducted at 11 a.m. at an altitude of 50 meters to capture high-resolution images, taking photos every 2 seconds with a 70% overlap. A linear flight plan was generated, and the flight parameters, such as takeoff speed (15 m/s) and flight speed (5.5 m/s), were configured. The drone followed the programmed route, returning to the takeoff point for battery replacement three times. All information was stored in the drone's memory and then processed using Agisoft Metashape software, where the images were imported, oriented in high quality, and a dense point cloud was created for the final analysis.




Figure 4. PCI evaluation by flying the DJI Mavic 2 pro Drone.

4. Results

4.1. International Roughness Index Evaluation

The Merlin Roughness Meter test was conducted on both lanes of a 2 km road section. Measurements began at kilometer marker 0+000 km and extended to 2+000 km, with records taken every 400 meters. On the right lane, readings were taken first on the right track and then on the left track, with a total of 200 readings per section. The same procedure was replicated on the left lane, maintaining the same interval and measurement methodology.

As for the evaluation using the Roadroid application, the analysis sections were also defined every 400 meters, with 200 continuous readings per lane. The data obtained was electronically processed, following the established methodology to segment the pavement into 5 evaluation sections for each lane and traffic direction. Since using the Roadroid app requires a license, an investigative request was made, resulting in the acquisition of a temporary free license.

4.1.1. IRI With Merlin Roughness Meter

Figure 5 shows the results for the IRI for the right lane evaluated using the Merlin Roughness Meter. It can be seen that the highest IRI value, 1.85, occurs in the section from 0+800 to 1+200.




Figure 5. IRI right lane Merlin roughness tester.

Figure 6 shows the results for the IRI for the left lane evaluated using the Merlin Roughness Meter. It can be seen that the highest IRI value, 1.88, occurs in the section from 0+000 to 0+400.




Figure 6. IRI left lane Merlin roughness tester.

4.1.2. IRI with the Roadroid Application

Figure 7 shows the results for the IRI for the right lane evaluated using the Roadroid app. It can be seen that the highest IRI value, 1.72, occurs in the section from 0+800 to 1+200.




Figure 7. IRI right lane using ROADROID.

Figure 8 shows the results for the IRI for the left lane evaluated using the Roadroid app. It can be seen that the highest IRI value, 1.60, occurs in the section from 0+800 to 1+200.




Figure 8. IRI left lane using ROADROID.

4.1.3. Comparison of IRI Using Merlin Roughness Meter and Roadroid

Table 3 shows that the average roughness value measured using the Merlin Roughness Meter for the right lane was 1.63 m/km, while for Roadroid it was 1.57 m/km, with an average variation of 4.007%. It can be concluded that there is a high correlation between the IRI and the eIRI found in the right lane. Table 4 shows that the average roughness value measured using the Merlin Roughness Meter for the left lane was 1.7 m/km, while for Roadroid it was 1.56 m/km, with an average variation of 8.7%. It can be concluded that there is a high correlation between the IRI and the eIRI found in the left lane.

It is concluded that using the Roadroid application yields results similar to those obtained with the Merlin method, making it a reliable option for monitoring road conditions.

Table 2. Comparative table between the IRI results with both teams—Right Lane.

Progression		MERLIN	ROADROID	Variation
Start	End	IRI	eIRI	
(Km)	(Km)	(m/Km)	(m/Km)	(%)
0+000	0+400	1.558	1.403	9.949
0+400	0+800	1.604	1.597	0.422
0+800	1+200	1.851	1.716	7.282
1+200	1+600	1.682	1.562	7.174
1+600	2+000	1.456	1.547	6.222
Average		1.630	1.565	4.007

Additionally, Figure 9 shows the scatter plot of IRI vs eIRI for the right lane data. The best-fit line to the point cloud with the origin point (0,0) is displayed, with the IRI values on the “x” axis and eIRI values on the “y” axis. A coefficient of determination (R^2) of 0.9967 is obtained, indicating a high correlation (Figure 3).




Figure 9. IRI vs eIRI dispersion table—Right Lane.

Table 3. Comparative table between the IRI results with both teams—Left Lane.

Progression		MERLIN	ROADROID	
Start	End	IRI	eIRI	Variation
(Km)	(Km)	(m/Km)	(m/Km)	(%)
0+000	0+400	1.88	1.57	16.53
0+400	0+800	1.72	1.58	8.22
0+800	1+200	1.66	1.56	6.05
1+200	1+600	1.70	1.60	5.72
1+600	2+000	1.54	1.45	5.89
Average		1.700	1.552	8.71

Figure 10 shows a linear regression for the left lane data. The best-fit line to the point cloud with the origin point (0,0) is displayed, with the IRI values on the “x” axis and eIRI values on the “y” axis. A coefficient of determination (R^2) of 0.998 is obtained, also indicating a high correlation.




Figure 10. IRI vs eIRI dispersion table—Left Lane.

4.1.4. Comparison of PSI Using the Merlin Roughness Meter and Roadroid

The PSI results using both devices for the right lane are shown in Table 43. For the right lane, employing the Merlin Roughness Meter, the quantitative PSI value was 3.72, categorized as GOOD on the qualitative scale. Using the Roadroid application, the quantitative PSI value was 3.76, also categorized as GOOD. The proximity of these values and their identical qualitative scale (GOOD) demonstrate a strong correlation between the PSI measurements for the right lane, with a maximum difference of 1.1% in their quantitative values.

Table 4. Comparative table between the PSI results with both teams—Right Lane.

PROGRESSION		MERLIN	ROADROID	SERVICEABILITY			
START	END	IRI	eIRI	VALUE		SCALE	SCALE
(Km)	(Km)	(m/Km)	(m/Km)	PSI- MERLIN	PSI- ROADROID	(-)	(-)
0+000	0+400	1.56	1.40	3.77	3.87	GOOD	GOOD
0+400	0+800	1.60	1.60	3.74	3.74	GOOD	GOOD
0+800	1+200	1.85	1.72	3.57	3.66	GOOD	GOOD
1+200	1+600	1.68	1.56	3.68	3.76	GOOD	GOOD
1+600	2+000	1.46	1.55	3.84	3.77	GOOD	GOOD
AVERAGE				3.72	3.76	GOOD	GOOD

The PSI results for both devices on the left lane are also shown (Table 4). For the left lane, the Merlin Roughness Meter yielded a quantitative value of 3.67, within the GOOD qualitative scale, while the Roadroid application gave a quantitative value of 3.77, also within the GOOD qualitative scale. These similar values and the identical qualitative scale (GOOD) demonstrate a good correlation between the PSI measurements for the left lane, with a maximum difference of 3% in their quantitative values.

Table 5. Comparative table between the PSI results with both teams—Left Lane.

PROGRESSION		MERLIN	ROADROID	SERVICEABILITY			
START	END	IRI	eIRI	VALUE		SCALE	SCALE
(Km)	(Km)	(m/Km)	(m/Km)	PSI- MERLIN	PSI- ROADROID	(-)	(-)
0+000	0+400	1.88	1.57	3.55	3.76	GOOD	GOOD
0+400	0+800	1.72	1.58	3.66	3.75	GOOD	GOOD
0+800	1+200	1.66	1.56	3.70	3.77	GOOD	GOOD
1+200	1+600	1.70	1.60	3.67	3.74	GOOD	GOOD
1+600	2+000	1.54	1.45	3.78	3.84	GOOD	GOOD
AVERAGE				3.67	3.77	GOOD	GOOD

4.1.5. Analysis of Unit Prices for Obtaining IRI with Roadroid and the Merlin Roughness Meter

Table 6. Unit price to obtain IRI with Roadroid.

Item	Specification	Unit	Quantity	Unit Price	Subtotal
Labor	Civil Engineer (specialist)	Hh	2.00	500.00	1000.00
Vehicle	Medium car rental	Day	1.00	356.00	356.00
Gasoline	84 octanes	GL	0.07	13.86	0.91

Equipment	Android cell phone	Day	1.00	2.47	2.47
	Annual license for 1 user	Day	1.00	3.19	3.19
				TOTAL	1362.57
				UP (Soles/Km)	S/ 681.29

Table 7. Unit price to obtain IRI with the Merlin Roughness Tester.

Item	Specification	Unit	Quantity	U.P.	Total
Field Work	Laborer (watchman)	Hh	8	39.1	312.96
	Technician	Hh	8	54.98	439.84
Field Work	Civil Engineer	Hh	2	150	300
Equipo	Merlin Roughness Tester	Day	1	750	750
TOTAL					1802.80
UP (Soles/Km)					S/ 901.40

For evaluating 1 km of the AR-780 road, there is a difference in unit costs. The cost for evaluating roughness with the Roadroid application is 681.29 Peruvian soles, compared to 901.40 Peruvian soles for the Merlin Roughness Meter, resulting in a positive profitability margin of 24.42%.

The Roadroid application’s performance is 1.08 km/min, as the vehicle traveled at an approximate speed of 75 km/h. In contrast, the traditional Merlin Roughness Meter has a performance of 1 km/h. This indicates that the data collection process using the Roadroid application is 60 times faster. Therefore, it is concluded that the use of the Roadroid application is not only more economical but also more cost-effective.

Figure 11 shows the Cost-Benefit analysis between these two methods, indicating that the Roadroid application is more efficient in terms of time and cost for measuring IRI over 1 kilometer of road, with a time of 1 minute and a cost of 681.29 soles per km, compared to 60 minutes and a cost of 901.4 soles per km using the Merlin Roughness Meter.




Figure 11. Cost Benefit in time between the Merlin Roughness Tester and ROADROID.

4.2. Pavement Condition Index (PCI) Evaluation

In the study conducted along 2 km of the AR-780 Polobaya road to evaluate the Pavement Condition Index (PCI) through visual inspection, 67 sample units were used. Each unit measured 30 m in length and 7.6 m in width, covering an area of 228 m², except for unit UM-67, which covered 152 m².

For the PCI evaluation using a drone, a DJI Mavic 2 Pro was employed, programmed with a mobile phone. The flight took place at 11 a.m., following the guidelines of the NTC 001–2015 standard [23]. A height of 50 meters was set, allowing high-resolution images to be captured without interference on the road. Photographs were taken every 2 seconds, with a 70% crosswise and lengthwise overlap, ensuring adequate image overlap to obtain enough homologous points. The drone’s software automatically calculated the number of points, the number of photos, and the flight time.

For the PCI evaluation using a drone, a DJI Mavic 2 Pro was employed, programmed with a mobile phone. The flight took place at 11 a.m., following the guidelines of the NTC 001–2015 standard [23]. A height of 50 meters was set, allowing high-resolution images to be captured without interference on the road. Photographs were taken every 2 seconds, with a 70% crosswise and lengthwise overlap, ensuring adequate image overlap to obtain enough homologous points. The drone’s software automatically calculated the number of points, the number of photos, and the flight time.

4.2.1. Comparison between the Pavement Condition Index (PCI) Using Visual Inspection and Drone Flight

In Figure 12, PCI data for each 30 m sample unit can be visualized using both methodologies and a bar graph also represents the average PCI value for both methodologies.




Figure 12. PCI values calculated for both methodologies.




Figure 13. PCI values calculated for both methodologies.

In response to the values presented in the comparison of the PCI between both methodologies—through the conventional method of visual inspection of failures and via drone flight (DJI Mavic 2 Pro)—for the AR-780 road, the average PCI value through the conventional visual inspection method was 76.75, and for the DJI Mavic 2 Pro drone, it was 82.04, with an average variation of 6.89%.

Therefore, it can be concluded that the PCI measurement using the traditional method provides greater accuracy and detail since it is conducted in the field and yields better results for pavement failures compared to the method using the DJI Mavic 2 Pro drone. The results obtained by the drone can be optimized by complementing it with topographic leveling; the drone did not offer higher precision because it is not the appropriate equipment for z-axis measurement, which requires millimetric precision for this study. The photogrammetry performed with the drone does not have the appropriate z-axis precision.

4.2.2. Comparison between the Pavement Condition Index (PCI) Using Visual Inspection and Drone Flight

In response to the values presented in the comparison of the intervention range between both methodologies—through the conventional method of visual inspection of failures and via drone flight (DJI Mavic 2 Pro)—for the AR-780 road, the PCI of the AR-780 local road was determined through conventional failure inspection, obtaining 50 sample units that require maintenance and 17 units that require rehabilitation (2, 7, 9, 10, 12, 17, 25, 32, 35, 36, 39, 40, 45, 49, 52, 54, and 56). Meanwhile, using the drone method for PCI, 62 sample units were found to require maintenance and 5 units to require rehabilitation. It is notable that both methods coincided on 5 sample units requiring rehabilitation intervention: UM-09, 10, 17, 39, and 40; and 50 sample units suggested maintenance intervention, with 12 sample units differing in their intervention range.

It can be concluded that PCI measurement using the traditional method provides greater accuracy and detail since it is conducted in the field and yields better results for pavement failures compared to the method using the DJI Mavic 2 Pro drone.




Figure 14. PCI for both types of evaluation and their respective classification.

Table 8. Intervention range for each methodology.

TYPE OF EVALUATION	PCI	CLASSIFICATION
Conventional PCI Method	76.75	VERY GOOD
PCI Method using a drone	82.04	VERY GOOD

4.2.3. Unit Price Analysis to Obtain PCI Using Drone Flight and Visual Inspection

Tables 9 and 10 show the unit cost analysis for the PCI test through conventional visual inspection for 2 km, with a cost of 1,422.73 soles per kilometer of road. In the next table, the price of the PCI test using a drone for 2 km is shown, with a cost per kilometer of 375 soles. Comparing both costs, a reduction of 73.6% is achieved using the drone evaluation method.

Table 9. PCI measurement using conventional visual inspection for 2 km.

PCI measurement service by conventional visual inspection for 2km					
Item	Specification	Unit	Quantity	U.P.	Subtotal
Labor	Civil Engineer (specialist)	Hh	30	80.00	2400
	Assistant	Hh	30	10.00	300
Materials	Spray	Und	3	15.5	46.5
	Laminated board 0.60m x 0.80m	Und	1	53	53
	Whiteboard markers	Und	3	3.6	10.8
	28" Safety cones	Und	1	29.5	29.5
Equipment	50 m measuring tape	Day	1	2.47	2.47
	8 m measuring tape	Day	1	3.19	3.19
TOTAL					2845.46
UP (Soles/Km)					S/ 1,422.73

Table 10. PCI measurement using the application for 2 km.

Specification	Unit	Quantity	U.P.	Total
Civil Engineer (specialist)	hh	3	116.67	350
Assistant	hh	3	16.67	50
Mavic 2 Pro Drone	glb	1	350	350
Android Cell Phone	glb	1		0
TOTAL				750.00

UP (Soles/Km)	S/	375.00
---------------	----	--------

In Figure 15, a cost-benefit analysis between the traditional system and the method using a drone is observed, obtaining lower costs and time using a drone, which is 375 soles and 3 hours, compared to the traditional method, which is 1,422.73 soles and 30 hours.




Figure 15. Cost-benefit analysis between the traditional system and the method using drone.

4.3. Proposal for Maintenance Management on Local Roads

In proposing a maintenance management plan for local roads, it is worth mentioning that local governments are responsible for local roads. By applying Smart technologies, they can measure the IRI (International Roughness Index) and PCI (Pavement Condition Index) to get an overview of the roads needing maintenance and thus have information about the current functional condition of their roads and determine what type of maintenance is required.

In the department of Arequipa, there are 149.64 km of paved local roads managed by their respective local governments, according to the update of [24], which involve execution costs and operational expenses for their corresponding routine maintenance.

Therefore, this technical and economic proposal aims to intervene in local roads to facilitate and shorten the evaluation time and reduce costs.

By operating for the 149.64 km of local roads in the city of Arequipa at the unit cost for evaluating IRI obtained by the Roadroid method, the result is 101,947.68 soles. For the Merlin Roughness Meter method, the result is 134,885.50 soles, achieving savings of 32,937.82 soles with the Roadroid method.

Also, by operating for the 149.64 km of all local roads in Arequipa at the unit cost to evaluate PCI, the total cost obtained is 202,897.32 soles using the conventional method and 56,115.00 soles using the drone method, generating savings of 146,782.32 soles for the respective entity if this method is used.

5. Discussion

This research has considered it essential to divide the discussion into five key terms that reflect the relevance and scope of this study.

5.1. Roughness Indicator

The IRI results obtained in this research present a moderate relationship compared to the findings of Castillo and Morales [25]. In my study, the IRI variation between the Merlin roughness meter and the Roadroid application ranges from 0% to 8.71%, while Castillo and Morales [25] report

a difference of up to 27.5%. This discrepancy can be attributed to the conditions under which each study was conducted. Castillo's research was carried out on a busy avenue, subject to factors such as variable speed, the presence of speed bumps, and fluctuations in traffic flow. In contrast, my research was conducted on a local road, free from such influences, which may have favored greater consistency in the IRI results.

5.2. Serviceability Indicator

The PSI results in this research show a low correlation compared to those obtained by Mamani A. and Lozano R. [19]. In my study, the average PSI was 3.7 with both the Roadroid application and the Merlin roughness meter, while Mamani reports a PSI of 1.99. This suggests that the flexible pavement of the AR-780 local road is in better condition than that of Antúnez de Mayolo Avenue in Tacna. Additionally, the importance of comparing PSI data with a conventional method to ensure greater accuracy in the results is highlighted. In this regard, the Merlin roughness meter is a recommended method for such comparison.

5.3. Pavement Condition Indicator

Compared to the research by Cubas [15], the Pavement Condition Index (PCI) results in my study show a high correlation. In my research, the conventional and drone-based PCI evaluations yielded results of 76.75 and 82.04, respectively, while Cubas [15] reported values of 59 for the conventional evaluation and 61 for the drone evaluation. These results reflect an agreement between both studies in that conventional visual inspection proves to be more accurate in evaluating the pavement condition PCI. This difference is due to the fact that drones, in the context of this study, which requires millimetric precision, do not provide the necessary accuracy on the z-axis. The photogrammetry performed with drones does not achieve the required precision on that axis.

5.4. Intervention Range Indicator

Compared to the research by Cubas [15], the Pavement Condition Index (PCI) results in my study show a high correlation. In my research, the PCI values obtained through conventional and drone methods indicate the need for intervention in the maintenance range. In contrast, the results of Cubas [15] suggest that both the conventional and drone-based evaluations correspond to an intervention range for rehabilitation and structural reinforcement. This suggests that the local road analyzed in my study requires corrective maintenance due to its incipient failures, while the avenue studied by Cubas [15] needs medium-term rehabilitation.

5.5. Maintenance Management Indicator

In my research, the evaluation using drones takes 3 hours, while the traditional method requires 30 hours to cover the entire study area. This demonstrates that the use of drones is approximately 10 times faster in terms of time. Regarding cost, the evaluation with drones incurs a cost of 375.00 soles per kilometer, compared to 1,422.73 soles per kilometer with the traditional method, representing a 73.64% reduction in costs. Therefore, drone inspection is significantly more economical than conventional visual inspection.

The research conducted by Colque [26] reports that the total drone usage time to evaluate two avenues was 4 hours, with a total cost of 4,650.25 soles.

In conclusion, both this research and that of Colque [26] show a significant reduction in costs and execution time when using drones for pavement evaluation.

6. Conclusions

This research determined the roughness value using the traditional Merlin Roughness Meter method and the Roadroid application. The average roughness value using the Merlin Roughness Meter test for the right lane was 1.63 m/km, and for Roadroid, it was 1.57 m/km, with an average variation of 4.007% and a correlation coefficient R^2 of 0.997. It can be concluded that there is a high

relationship between the IRI and eIRI found in the right lane. The average roughness value using the Merlin Roughness Meter test for the left lane was 1.7 m/km, and for Roadroid, it was 1.56 m/km, with an average variation of 8.71% and a correlation coefficient R^2 of 0.998. It can be concluded that there is a high relationship between the IRI and eIRI found in the left lane. Therefore, it is concluded that using the Roadroid application provides results similar to those obtained with the Merlin method, making it a reliable option for monitoring road conditions.

The Present Serviceability Index (PSI) for the AR-780 road using the Merlin Roughness Meter test for the right lane had an average quantitative value of 3.72, and using the Roadroid application, it was 3.76, both falling within the qualitative scale of GOOD. The PSI value for the left lane using the Merlin Roughness Meter test had an average quantitative value of 3.67, and using the Roadroid application, it was 3.77, both falling within the qualitative scale of GOOD. It is concluded that the Roadroid application provides reliable data because the PSI values obtained are close to those obtained by the Merlin method, with a maximum difference of 3% in their quantitative values for the road under study.

The PCI value was determined using the conventional method of visual inspection of failures and through the flight of the DJI Mavic 2 Pro drone. The average PCI value using the conventional visual inspection method was 76.75, and for the DJI Mavic 2 Pro drone, it was 82.04, with an average variation of 6.89%. Therefore, it can be concluded that the PCI measurement using the traditional method provides greater accuracy and detail, as it is conducted in the field and yields better results for pavement failures compared to the method used by the DJI Mavic 2 Pro drone. The results obtained by the drone can be optimized by complementing them with topographic leveling. The drone did not offer higher precision because it is not the appropriate equipment for z-axis measurement, which requires millimetric precision for this study. The photogrammetry performed with the drone does not have adequate z-axis precision.

The PCI of the AR-780 local road was determined through a conventional failure inspection, obtaining 50 sample units that require maintenance and 17 units that require rehabilitation (2, 7, 9, 10, 12, 17, 25, 32, 35, 36, 39, 40, 45, 49, 52, 54, and 56). Using the drone method for PCI, 62 sample units were found to require maintenance and 5 units to require rehabilitation. It can be observed that in both methods, there is a coincidence in 5 sample units that require rehabilitation intervention: UM-09, 10, 17, 39, and 40; and 50 sample units suggest maintenance intervention, with 12 sample units not matching in their intervention range. Therefore, it can be concluded that the PCI measurement using the traditional method provides greater accuracy and detail, as it is conducted in the field and yields better results for pavement failures compared to the method used by the DJI Mavic 2 Pro drone. The results obtained by the drone can be optimized by complementing them with topographic leveling. The drone did not offer higher precision because it is not the appropriate equipment for z-axis measurement, which requires millimetric precision for this study. The photogrammetry performed with the drone does not have adequate z-axis precision.

The efficiency of the smart technologies used in this research for local road maintenance management was evaluated. In terms of time and cost when implementing the Roadroid application compared to the Merlin method, it was found that with the application, 1 km/min can be covered, while with the Merlin method, it is 1 km/h, indicating that the application is 60 times faster in data collection than the Merlin method. Regarding cost, with Roadroid, a Unit Price Analysis per kilometer of 681.29 soles was obtained, and with the Merlin method, it was 901.40 soles, making the use of the Roadroid application more economical with a profitability percentage of 24.42%. Through the Cost-Benefit analysis, it is concluded that the Roadroid application is more efficient in terms of data collection time and costs, achieving similar precision in the results. As for PCI measurement on the road, using the drone takes 3 hours, and with the traditional method, it takes 30 hours for the entire study area, indicating that the use of drones is 10 times faster in terms of data collection and analysis time. Regarding cost, with the drone, a Unit Price Analysis per kilometer of 375.00 soles was obtained, and with the traditional method, it was 1422.73 soles, making it more economical with a profitability percentage of 73.64%. Through the Cost-Benefit analysis, it is concluded that the use of drones is more efficient in terms of data collection and analysis time and also in costs. However, the

use of the traditional method to obtain the PCI of the road is more accurate than that obtained by the drone.

Author Contributions: Conceptualization, L.F.J.G., R.G.T. and A.J.E.V.; methodology, L.F.J.G., R.G.T. and A.J.E.V.; software, L.F.J.G.; validation, L.F.J.G.; formal analysis, L.F.J.G.; investigation, L.F.J.G.; resources, L.F.J.G.; data curation, L.F.J.G.; writing—original draft preparation, L.F.J.G.; writing—review and editing, L.F.J.G., R.G.T. and A.J.E.V.; visualization, L.F.J.G.; supervision, L.F.J.G., R.G.T. and A.J.E.V.; project administration, L.F.J.G. All authors have read and agreed to the published version of the manuscript.

Funding: This research received no external funding.

Data Availability Statement: The findings of this research are supported by the data available from the corresponding author, L.F.J.G., upon reasonable request.

Acknowledgments: The authors thank Manuel Luque Delgado for his unconditional support and constant motivation, Diego Gómez Quispe for his support during the formatting of the document and Universidad Católica de Santa María for providing useful insight and assistance with the research reported, particularly the research group DROP.

Conflicts of Interest: The authors declare no conflicts of interest.

References

1. Cruz Toribio, J.; Gutiérrez Lázares, J. Cálculo del índice de condición del pavimento con imágenes del vehículo aéreo no tripulado. Universidad de Ingeniería, Lima, Perú, 2018.
2. Scholotjes, M.R.; Visser, A.; Bennet, C. EVALUATION OF A SMARTPHONE ROUGHNESS METER. **2014**.
3. Llapasi. La importancia del mantenimiento de las carreteras. Available online: <https://llapasi.com/sin-categoria/la-importancia-del-mantenimiento-de-las-carreteras/> (accessed on 13 septiembre 2024).
4. Espinoza Vigil, A.J.; Carhart, N.J. Local infrastructure governance in Peru: a systems thinking appraisal. *Infrastructure Asset Management* **2024**, *11*, 145-160, doi:10.1680/jinam.22.00037.
5. Ccancapa Puma, J.; Hidalgo Valdivia, A.V.; Espinoza Vigil, A.J.; Booker, J. Preserving Heritage Riverine Bridges: A Hydrological Approach to the Case Study of the Grau Bridge in Peru. *Heritage* **2024**, *7*, 3350-3371.
6. Espinoza Vigil, A.J.; Booker, J. Hydrological Vulnerability Assessment of Riverine Bridges: The Bajo Grau Bridge Case Study. *Water* **2023**, *15*, 846.
7. Huarca Pulcha, A.; Espinoza Vigil, A.J.; Booker, J. Prioritizing Riverine Bridge Interventions: A Hydrological and Multidimensional Approach. *Designs* **2023**, *7*, 117.
8. Espinoza Vigil, A.J.; Booker, J.D. Building national disaster resilience: assessment of ENSO-driven disasters in Peru. *International Journal of Disaster Resilience in the Built Environment* **2023**, *14*, 423-433, doi:10.1108/IJDRBE-10-2022-0102.
9. Sánchez, J.C. Evaluación del estado del pavimento de la Av. Ramón Castilla, Chulucanas, mediante el método PCI. Universidad de Piura, Piura, Perú, 2017.
10. ECOASFALT. Consecuencias del asfalto en mal estado de conservación. Available online: <https://www.ecoasfalt.es/consecuencias-del-asfalto-en-mal-estado-de-conservacion/> (accessed on 13 Septiembre 2024).
11. Velásquez, J.C. Caracterización y análisis del método ROADROID en la obtención del índice de rugosidad internacional (IRI) para la gestión de pavimentos. Universidad Nacional de Ingeniería, Lima, Perú, 2021.
12. Arianto, T.; Suprpto, M.; Syafi'i. Pavement Condition Assessment Using IRI from Roadroid and Surface Distress Index Method on National Road in Sumenep Regency. *Engineering* **2018**, *8*.
13. Oblitas Gastelo, B.E.; Medina Cardozo, I.I.; Paredes Asalde, C.R. Índice de regularidad internacional e índice de condición de pavimento para definir niveles de serviciabilidad de pavimentos. **2021**, *18*, 2-3, doi:10.15332/iteckne.v18i2.2616.
14. Sarabia, W. Evaluación de fallas superficiales del pavimento flexible por el método PCI y empleo del Dron, Carretera Covadonga—Mollepata, Ayacucho. Universidad César Vallejo, Ayacucho, Perú, 2021.
15. Cubas, J. Uso de un dron para optimizar la evaluación superficial del pavimento flexible por el método PCI en la Av. Los Conquistadores, distrito de San Isidro, Lima. Universidad Privada del norte, Lima, Perú, 2021.
16. Perú, G.d. Clasificador de Rutas del Sistema Nacional de Carreteras—SINAC. **2008**.
17. Putra, D.A.; Suprpto, M. Assessment of the road based on PCI and IRI roadroid measurement. *MATEC Web Conf.* **2018**, *195*, 04006.
18. Mozo Barrantes, W.V.; Quispe Mendoza, A.J. Evaluación superficial de la condición y serviciabilidad del pavimento flexible por el método pavement condition index (PCI) y ROADROID en el circuito humedal Lucre-Huacarpay. Universidad Andina del Cusco, Cusco, Perú, 2019.

19. Mamani A., D.E.; Lozano R., J.L. Evaluación de la rugosidad en el pavimento utilizando teléfonos inteligentes para mejorar la transitabilidad vehicular en la Av. Antúnez de Mayolo, distrito Gregorio Albarracín Lanchipa, Tacna. Universidad Privada de Tacna, Tacna-Perú, 2021.
20. A. Gabbar, H.; Chahid, A.; U. Isham, M.; Grover, S.; Singh, K.P.; Elgazzar, K.; Mousa, A.; Ouda, H. HAIS: Highways Automated-Inspection System. *Technologies* **2023**, *11*, 1-3.
21. Roadriod. Available online: <https://www.roadroid.com/map> (accessed on 13 septiembre 2024).
22. International, A. ASTM D6433-20. Standard Practice for Roads and Parking Lots Pavement Condition Index Surveys **2023**, doi:10.1520/D6433-20.
23. Ministerio de Transportes y Comunicaciones. Norma Técnica Complementaria. **2015**.
24. Perú, G.d. Convenio de Gestion para la ejecucion del mantenimiento rutinario de vías vecinales entre provias descentralizado y la municipalidad provincial de Arequipa. **2023**.
25. Castillo, R.; Morales, Y. Optimización de la evaluación funcional del pavimento flexible mediante el software roadroid y el método merlón de la Av. prolongación Iquitos-Lince-Lima-2022. Universidad Privada del Norte, Lima, Perú, 2023.
26. Colque, J. Aplicación del método PCI en pavimentos flexibles empleando drones. Universidad Peruana los Andes, Huancayo, Perú, 2023.

Disclaimer/Publisher's Note: The statements, opinions and data contained in all publications are solely those of the individual author(s) and contributor(s) and not of MDPI and/or the editor(s). MDPI and/or the editor(s) disclaim responsibility for any injury to people or property resulting from any ideas, methods, instructions or products referred to in the content.